

Gauge list

No	Name	SPS/A-B1201□			
		H(Heavy materials)	M(Medium materials)	L(Light materials)	K(Knitted materials)
1	Thread take-up lever (ass' y) 	▽ 08S001P-306H		△ 08S001S-306H	
2	Link cam 	02-002A-120H		△ 02S002S-306H	
3	Thread guide of needle bar 	04-007A-120H	04-008A-120M		
4	Needle	DP × 17 #19	DP × 5 #16 (DP × 5 #14)	DP × 5 #11	
5	Shuttle race ring 	07-021A-120H	07-022A-120H	07-023A-120L	
6	Shuttle 	07-028A-120H	07-029A-120M		
7	Shuttle upper spring 	◇ 07S040S-306G		07-041G-120L 07-040G-120L	
8	Thread tension control device 	○ 40S001S-306H	◇ 40S001S-306G		
9	Needle plate cover 	10-041A-120H	10-042A-120M	10-043A-120K	
10	Trimming lever-B 	◇ 10S055S-306G			
11	Lifting lever spring 	22-016G-120H	22-016G120M		
12	Presser foot (left) 	22-019A-120H	22-021A-120M	22-023A-120L	22-023A-120K 22-123A-120K
13	Presser foot (right) 	22-019A-120H	22-022A-120M	22-024A-120L	22-024A-120K 22-124A-120K
14	Feeding plate 	22-029A-120H	22-030A-120M	22-033A-120L 22-034A-120L (without knurling)	22-035A-120K 22-135A-120K (without knurling)

NOTE) ○ : Common use with SPS/A-1306H ( ) types (Heavy materials)
◇ : Common use with SPS/A-1306G ( ) types (Medium materials)
△ : Common use with SPS/A-1306 ( ) S types (Standard stitch)
▽ : Common use with SPS/A-1306 ( ) P types (Perfect stitch)

www.promelectroavtomat.ru